VL100,VL110 & VL300
 v1.3.38

 VP100 & VP300
 v1.1.24

 VL500
 v2.0.22

 VP500
 v1.2.8

Release Notes>

82023 valorpaytech.com




CONTENTS

P 03	Allow Additional Inputs on Refund
P 03	Enable Backlight for Keypad
P 04	New Settlement Report Features
P 04	Increased Receipt Font Clarity
P 05	Password prompt for Cash Sale
P 05	Transactions Module
P 07	Dual Pricing - Enter Card Amount
P 07	Menu & Inventory
P 08	True Surcharge Calculation - VISA
P 09	Display Font Size Increased
P 10	New APN Added
P 10	Tip on Screen Larger Tip Suggestion
P 11	Bug Fixes

Allow Additional Inputs on Refund

DEVICES: VL100, VL110, VP100, VL500 and VP500


Terminals allow additional input entries for 'Refund Transactions' if 'Additional Input 1' and/or 'Additional Input 2' are enabled in the Valor Portal.



Enable Backlight for Keypad

DEVICES: VL100, VL110 and VL300

Terminals allow the option to enable or disable the backlight for the keypad within the 'Setup' menu, titled 'KBD Backlight'.




New Settlement Report Features

DEVICES: VL100, VL110, VP100, VL500 and VP500

The Settlement Report will be printed by terminals only when the "SETTLEMENT REPORT SUMMARY" option is enabled within the Valor Portal under the "RECEIPT" settings.

Furthermore, attempting a Batch Settlement with no transaction batches will result in a small printout stating "No Transactions to Settle". These options are enabled by default.



Increased Receipt Font Clarity

DEVICE: VP100

The font and font size on the terminal receipts have been changed to enhance visibility.



ERNEST FREDDIE DAYTON OH 45454 564-984-9848 07/19/2023 05:59 Sale Trans:2 Batch:2 MASTERCARD CHTP ********** **/** \$100.00 AMOUNT: **\$1.00** \$2.00 TIP: State Tax Non-Cash \$3.03 Charge SUB TOTAL: \$106.03 TIP: TOTAL: Resp: APPROVAL VTLMC1 Code: VTLMC1 Ref#: 320009500443 App Name: Debit Mastercard AID: A0000000041010


OLD RECEIPT

NEW RECEIPT

Password Prompt for Cash Sales

DEVICES: VL100, VL110 and VP100


Terminals will prompt for a password for cash sales when the 'Prompt Password for Cash Sales' option is set to 'Yes' under the 'Dual Pricing' homescreen setting on the Valor Portal.



Transactions Module

DEVICES: VL500 and VP500

Users can view each transaction from any batch from any particular date. By selecting a specific batch of their preference, they gain access to all transactions within that batch.



Users can view the summary of all transactions within the open batch on their terminals.



Users can view the summary of all transactions from any of their closed batches on the terminals. They can initiate refunds for specific transactions of their choice.



Dual Pricing - Enter Card Amount


DEVICE: VP500

Terminals will enable users to enter the card amount in the Dual Pricing mode.

For example,

If the merchant enters \$10.40 on the terminal, it will display the following:


Card: \$10.40 Cash: \$9.98.



Menu & Inventory

DEVICE: VP500

Terminals will enable users to access the 'Inventory' or 'Menu' in the Dual Pricing Mode.



True Surcharge Calculation - VISA


DEVICES: VL100, VL110, VP100, VL500 and VP500

The terminals will recalculate and adjust the surcharge dollar amount to ensure it does not exceed 3% in order to comply with Visa requirements.

For example,

\$11.59 * 3% = \$0.3477. That will round up to \$0.35. \$2.24 * 3% = \$0.0672. That will round up to \$0.07.


To enable the 'validate fee' option, toggle under 'Device Parameters' to 'Yes'.





Display Font Size Increased

DEVICE: VP100

Application-wide improvements have been made to the font size and clarity of the VP100 POS Terminal.









New APN Added

DEVICE: VL110


A new Access Point Name (APN) has been added to the VL110 POS terminal.


APN:M2M005343.ATTZ

Tip on Screen | Larger Tip Suggestion

DEVICES: VL500 and VP500

The tip amount percentage options are displayed in a larger size for better visibility.





BEFORE

AFTER

BUG FIXES

Dual Pricing Calculation | Issue with dual pricing calculation corrected.

Keyboard Beep | Issue where pressing X takes user back to Homescreen instead of Setup screen corrected.

VL100/VL110/VP100 | Issue fixed where the device wont connect to Remote Diagnostics server when both RD and Valor Connect enabled.

VL110 | Issue with PREAUTH not being centered on Homescreen corrected.

VL300/VP300 | Issue with EBT CASH and EBT FOOD displays corrected.

VP300 | Device malfunction when some cards are swiped for refund transactions has been fixed in the latest firmware.

VL500 | Brightness utility corrected.

VL500 | Issue with EBT not working as expected on Dual Pricing Homescreen corrected.

VP100 | Issue where terminal freezes while attempting a transaction corrected.

VP100 | Issue with manual entry being possible when parameter is disabled corrected.

VP100 | Segmentation Fault issue corrected.

VP100 | Presents SQLite Error for the cards having SINGLE quotes on their CARDHOLDER name is fixed now.

THANK YOU

2 Jericho Plaza, Suite 304 Jericho, NY, 11753, United States

valorpaytech.com











Copyright © 2023, Valor PayTech, LLC. All rights reserved.

This document is protected by U.S. and International copyright laws. Reproduction and/or distribution



Scan the QR Code to Access Our Knowledge Base Articles



1.800.615.8755

sales@valorpaytech.com